



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES


### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director  
JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Report Date:

Supervisor 

**Mine Name:** Utah Marblehead Quarry  
**Operator Name:** Utah Marblehead, LLC

**Permit number:** M0450003  
**Inspection Date:** October 24, 2006  
**Time:** 12:30 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** none  
**Mine Status:** Inactive

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads,
8. Soils
9. Revegetation
10. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Inspection Summary:


1. This site has now been inactive for apparently more than 10 years. There was no signs of recent activity at the site other than recreational (ATV tracks). The area appeared to be stable with no evidence of offsite runoff.
5. The access (haul road) is stable for the most part. However, there was one area where a small gully has formed across the road (6-8 inches wide, 3-4 inches deep).
9. Volunteer vegetation has established an a significant portion of the more level areas of disturbance (mostly rabbitbrush). The vegetation test plots that were established in the '80's were also observed.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

1. Since this site has been inactive for more than ten years, the operator should be notified that reclamation needs to commence immediately or enforcement action may follow.

Continue to monitor this site when in the area.

**Inspector's Signature** 

**Date:** October 31, 2006

LK:pb

O:\M045-Tooele\M0450003 UtahMarbleheadQuarry\inspections\insp-10242006 2006.doc